New BioMini version (SUP-SFR-410) is supported in GPP version 2.4.038

From version 2.4.038, GuardPointPro supports the new SUPREMA BioMini USB reader

New version of Suprema BioMini (SUP-SFR-410) is supported from this GuardPointPro version after installing the required driver here.
Suprema BioMini (SUP-SFR-400) is still supported.

Important note:
If using BioMini that is not purchased from Sensor Access, during enrolment the user may have the following message: "Vendor ID is mismatched" which means that the scanner has another vendor ID.

To resolve this issue, contact your vendor or directly the Suprema support (support@supremainc.com) in order to receive the "UFLicense.dat" file that contains the right vendor ID.

Once the license file (UFLicense.dat) is received, place it in the application folder in order to replace the default one.